

1/11

100




FIG. 1

2/11




FIG. 2

3/11




FIG. 3




FIG. 4

4/11




FIG. 5




FIG. 6

5/11




FIG. 7

6/11




FIG. 8

7/11




FIG. 9

8/11







FIG. 10



10/11




FIG. 12

11/11

SCANNER APPARATUS

PC

CONNECT TO DESIGNATED IP ADDRESS
TO ESTABLISH CONTROL CONNECTION

220

USER anonymous

331

PASS anonymous

230

TYPE 0

200

PORT 10,11,12,13,4,26

200

STOR filename

150

CONNECT TO DESIGNATED
IP ADDRESS AND PORT NUMBER
TO ESTABLISH DATA CONNECTION

TRANSMIT TIFF FORMAT &
IMAGE FILE DATA SIGNAL

CUT-OFF DATA CONNECTION

QUIT

221

CUT-OFF CONTROL CONNECTION WITH PC

FIG. 13